. 1980/28 c.3 - 1799 071799 +

BMR PUBLICATIONS COMPACTUS (LENDING SECTION)

DEPARTMENT OF NATIONAL RESOURCES NATIONAL DEVELOPMENT



BUREAU OF MINERAL RESOURCES, GEOLOGY AND GEOPHYSICS

Record 1980/28

INVESTIGATION OF A SOIL DRAINAGE PROBLEM AT COOK PRIMARY

SCHOOL, ACT

by



P.D. HOHNEN

The information contained in this report has been obtained by the Department of National Resources as part of the policy of the Australian Government to assist in the exploration and development of neral resources. It may not be published in any form or used in a company prospectus or statement hout the permission in writing of the Director, Bureau of Mineral Resources, Geology and Geophysics.

Record 1980/28

INVESTIGATION OF A SOIL DRAINAGE PROBLEM AT COOK PRIMARY SCHOOL, ACT

by

P.D. HOHNEN


CONTENTS

		Page
ABS	TRACT	
INTRODUCTION		
INVESTIGATION		
CONCLUSIONS		
RECOMMENDATIONS		
æİ	FIGURES	
1.	Location map	
2.	Schematic cross section explaining seepage	
	PLATE	
1.	Groundwater seepage at Cook Primary School	

ABSTRACT

Permanent waterlogging of soils at several places in the grounds of Cook Primary School during the exceptionally wet years of 1973, 1974, and 1975, caused playing areas to deteriorate. The Department of Education requested that the Bureau investigate the seepages and propose remedial drainage measures.

Auger holes were drilled to determine soil properties. The seepage has been attributed to the intersection and partial removal of natural scil aquifers. Agricultural drains are recommended to reestablish permeable pathways for shallow groundwater. An alternative recommendation is to pump from a deep bore in the underlying fractured rock.



INTRODUCTION

Poorly drained soils at Cook Primary School (Fig. 1) lie within a partly dissected perched pediplain basin. An erosion gully had cut its way upslope through colluvium to the centre of the basin at the time the school grounds were landscaped in the late 1960s. Drainage and landscaping of the area, have completely hidden the location of the erosion gully, though presumably a storm water drain was installed in its vicinity before the area was landscaped.

Seepages were observed during an inspection of the grounds in 1975. All seepages were on gently sloping ground near the margins of the pediplain basin and less than 200 from the upslope limit of the erosion gully which drained the basin before development (Plate 1).

Foundations for the southern side of one of the school buildings were excavated below the natural groundsurface, and the batter slope between the school and Templetion Street is partly on fill materials (Fig. 2).

INVESTIGATION

Seven holes were drilled with an 'HDBA Proline Auger' until the drill bit would penetrate no further. Every hole filled with groundwater within a few days of drilling. Holes, 4,6, and 7 filled to their potentiometric levels within about an hour of completion of drilling. The holes were logged, and recovery tests were carred out on each hole to determine the in situ permeability of each aquifer intersected. A 'Honda'-powered diaphragm pump and 'Arkon' air-bleed recorder were used for the pumping and recovery operations.

Soil (aquifer) permeabilities determined from the recovery tests indicate that the most permeable soils lie between the church and Rowan Street(Plate 1). The permeabilities measured indicate that the soils are amenable to drainage by agricultural-type drains set within the aquifers at invert depths of not less than 90 cm.

CONCLUSIONS

- 1. Highly permeable colluvial fan and basin deposits, which are the transport medium for shallow drainage or interflow in the higher parts of Cook, have been intersected by the cut-and-fill processes of landscaping operations during the construction of Cook Primary School. This has allowed seepage from the colluvium, of water that was previously confined beneath low-permeability clay soils (Fig. 2).
- 2. Agricultural drains installed at depths of more than 90 cm as shown in Plate 1 would re-establish a permeable pathway for water percolating through soil materials.
- After installation of the drains, some temporary seepage may still occur in widely scattered areas within the school grounds during years with higher than average rainfall because soils in a downslope direction have a lower permeability and a reduced ability to transmit water. Water in excess of the amount that can be transmitted will appear as seepage at the surface.
- 4. An alternative method of draining the affected area would be to construct a bore and fit it with an electric submersible pump. This method relies on pumping from the underlying fractured-rock aquifer to lower the potentiometric surface of the soil aquifers, and has been successful in a similar situation at Red Hill. The depth of such a bore would be about 40-50 m, and drilling and completion of the bore would cost about \$5500; installation of a pump would be an additional charge.

RECOMMENDATIONS

It is recommended that agricultural drains be installed to drain the worst seepage areas on the southeastern—side of the school grounds in the corner formed by Templeton and Rowan Streets. It is proposed that the drains have a gradient of about 2.5% (1 in 40) and are connected to stormwater drains near Rowan Street.

Recommended drain routes are oriented to have the shortest paths and the steepest gradients that buildings, bicycle stands, and storm-water invert levels will allow.

SCHEMATIC CROSS SECTION EXPLAINING SEEPAGE AT COOK SCHOOL				
INSET - GENERALISED GROUNDWATER FLOW PATHS				
	School			
	1-1			
fill batter				
excavated mate	erials	root channel		
ground surface	page	perched		
12 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Diose Option Diversi			
X V		X _V		
V — inthe	2002 to 16 1	Arca of discharge		
Recharge or intake	area to aguiters h	from aguiters (sepage)		
South		North		
		School		
TV V V		natural ground surface		
TO A VALUE OF STATE O		excavated surbce		
V		soil)		
The state of the s				
Na Grand	/ v	/ V / V		
Sand Sand How path				
Y Volcanic rocks	SC W.F	CONTANT WITH DE ADELIA CO		
Bank ins	// pin rey	BUREAU OF MODERNAL RESOURCES CANDERPALACE TITLE		
	en es could Cesarger graype	Schematic Cross Section PROJECT		
	PH Construction Construction	Seepage at Cook Primary School		
	Supervisina apprilares	PDH 165/A16/2302		

